



Environmental Checklist

Material	Intentional added	Where / How Used
Antimony	0	Not used in Vette Products
Arsenic	0	Not used in Vette Products
Asbestos	0	Not used in Vette Products
Azo Colorants	0	Not used in Vette Products
Beryllium / Beryllium Compounds	0	Not used in Vette Products
Bismuth	0	Bismuth metal is included in a low melting
Brominated flame retardants other than PBBs and PBDEs	0	Not used in Vette Products
Cadmium	0	Not used in Vette Products
Formaldehyde	0	Not used in Vette Products
Gold	0	Not used in Vette Products
Hexavalent Chromium (Cr VI)	0	Not used in Vette Products
Lead (Plastics)	0	Not used in Vette Products
Lead (paints, packaging including semiconductor packaging)	0	Not used in Vette Products
Magnesium	0	Not used in Vette Products
Mercury	0	Not used in Vette Products
CFCs	0	Not used in Vette Products
HCFCs	0	Not used in Vette Products
HBFCs	0	Not used in Vette Products
Carbon Tetrachloride	0	Not used in Vette Products
Palladium	0	Not used in Vette Products
PBBs	0	Not used in Vette Products
PBDEs	0	Not used in Vette Products
PCBs	0	Not used in Vette Products
Polychlorinated Napthalenes (more than 3 chlorine atoms)	0	Not used in Vette Products
Phthalates	0	Not used in Vette Products
Radioactive Substances	0	Not used in Vette Products
Selenium	0	Not used in Vette Products
Short Chain Chlorinated paraffins	0	Not used in Vette Products
Tributyl tin	0	Not used in Vette Products
Triphenyl tin	0	Not used in Vette Products
Tibutyl Tin Oxide	0	Not used in Vette Products